



Western Michigan University  
ScholarWorks at WMU

---

Legacy Scout Tickets from Pure Oil Company

---

8-20-2021

**MGRRE\_PureOilScoutTickets\_Johnson, Rex\_2\_21081061310000**

MGRRE

*Western Michigan University*

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

---

#### WMU ScholarWorks Citation

MGRRE, "MGRRE\_PureOilScoutTickets\_Johnson, Rex\_2\_21081061310000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 3958.

<https://scholarworks.wmich.edu/pure/3958>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



---

**MGRRE\_PureOilScoutTickets\_Johnson, Rex\_2\_21081061310000**

API 21081061310000

Permit Number 6131

Lease Name Johnson, Rex

Well Number 2

County Kent

Township 06N

Range 12W

Section 5

2021 DEQ or Pure co\_name Goodale Enterprises LLC

Pure Number 80

Latitude 42.9422548

Longitude -85.7499783

## WELL REPORT - OUTSIDE OPERATIONS

SERIAL NO. 80STATE Michigan ~~XPSLX~~ Kent  
CO.OPERATOR Gordon Oil CompanyFARM Rex Johnson WELL NO. 2TWP. Walker S. 5 T. 6N R. 12W  
~~X SURVEY~~LOC. NE NW NEWILDCAT ☐ FIELD ☐ FIELD NAME \_\_\_\_\_

MAP NO. \_\_\_\_\_ CO-ORD. \_\_\_\_\_ ELEV. \_\_\_\_\_

STATUS \_\_\_\_\_

(Operator's name changed from  
Hartman Oil Co.)

NORTH

|  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|
|  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |

DATE 10-21-51 SCOUT DRS

**THE PURE OIL COMPANY**  
**LOCATION REPORT**

Date May 26, 1945 A.F.E. No. \_\_\_\_\_

Division Mich. Producing District \_\_\_\_\_ Lease Rex Johnson

Acres \_\_\_\_\_ Lease No. \_\_\_\_\_ Elevation \_\_\_\_\_ Well No. 2 (Serial No. 80)

Quadrangle NE NW NE Sec. 5 Twp. 6 N Rge. 12 W Twp. Walker

Survey \_\_\_\_\_ County Kent State Michigan

Operator Hartman Oil Co. Map Walker Township, Kent County

|       |                                 |
|-------|---------------------------------|
| _____ | Feet from North Line of Lease   |
| _____ | " " East " " "                  |
| _____ | " " South " " "                 |
| _____ | " " West " " "                  |
| _____ | Feet from North Line of Section |
| _____ | " " East " " "                  |
| _____ | " " South " " "                 |
| _____ | " " West " " "                  |

**LEGEND**

- |                         |                           |
|-------------------------|---------------------------|
| ○ Location              | ☉ Dry Showing Gas         |
| ☉ Gas Well              | ⊗ Abandoned Location      |
| ● Oil Well              | ☉ or ☉ Abandoned Gas Well |
| ☉ Gas - Distillate Well | ● or ● Abandoned Oil Well |
| ⊗ or ○ Dry Hole         | ● or ○ Input Well         |
| ● Dry Showing Oil       |                           |



See plat - Kent 80.

Remarks: Change of operator. Scale: \_\_\_\_\_

Submitted by \_\_\_\_\_ Approved by \_\_\_\_\_ Division Manager

Civil Engineer

Approved by \_\_\_\_\_ Vice-President-General Manager

Date May 15, 1939

# LOCATION REPORT

## THE LUBE OIL COMPANY

### THE LUBE OIL COMPANY

V.E. No.

DATE May 15, 1939

## LOCATION REPORT

No. 80

STATE Michigan COUNTY Kent DIST. Walker TWP. Walker SEC. 5 TOWN 6 N RANGE 12 W  
 WELL No. 2 (SERIAL No. 880) FARM Rex Johnson ACRES

NAME OF STREAM OR WATERS \_\_\_\_\_ QUADRANGLE NE-NW-NEOPERATOR Wolverine Natural Gas Company Map Walker Township, Kent County
25250 Feet from North Line of Farm  
11140 " " East " " "  
25250 " " South " " "  
11140 " " West " " "  
25250 Feet from North Line of Section  
1140 " " East " " "  
1140 " " South " " "  
1140 " " West 1/4 " "

## LEGEND

○ LOCATION

⊙ RIG

⊕ DRILLING

☀ GAS WELL

● OIL WELL

⊙ SMALL OIL WELL

⊙ DRY HOLE

⊙ DRY SHOWING OIL


⊙ DRY SHOWING GAS

⊙ ABANDONED LOCATION

⊙ ABANDONED GAS WELL

⊙ ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

P. L. J.  
 Superintendent or Foreman.



Michigan Producing Division

# PRODUCTION RECORD

## FORMATION AND CASING RECORD

Signed D. C. Shackelford